Γ	3/8" STEEL PLATE FORMED TO RADIUS OF PIPE, COAT W/CORROSION PREVENTATIVE TREATMENT
GROUT INSIDE SMOOTH W/RADIUS OF PIPE W/NON-SHRINK GROUT	SEAL PLATE TO PIPE W/APPROVED CAULKING
6x6 MESH CAST IN NON-SHRINK GROUT	FASTEN TO PIPE W/ 1/2" S.S. BOLTS, WASHERS & NUTS THROUGH PIPE AS SHOWN
<u>214 — STD RC PIPE REPAIR.</u> 214 — STD RC PIPE REPAIR.	C PIPE REPAIR ^{5/2016}

H:\Cad_Comn\Details Updated\0 - 200 - STORM complete\214 - Std RC Pipe Repair PLATE NAME:

CITY OF BLOOMINGTON MINESOTA 1700 W 98TH ST. BLOOMINGTON MN 55431 PHONE (952) 563-8700	214 - Std R	C Pipe Repair
ENGINEERING DIVISION	LAST REVISED: 9/14/2016	
PUBLIC WORKS DEPARTMENT	LAST REVISED BY: KBO	